

# Rate



# Card

- \* Branded spare parts will be charged at MRP
- \* Overall labour cost will not exceed INR 500
- \* The spare parts prices are not fixed it changes according to the ongoing market rate
- \* **NOTE** Final Repair cost is provided after inspection of AC

## Window AC Service/AC Installation Prices

Repair/Service	Service Charge (INR)
Wet Servicing	500
Dry Servicing	500
Jet Pump Servicing	1000
Installation	700
Un-Installation	500



## Split AC Service/AC Installation Prices

Repair/Service	Service Charge (INR)
Wet Servicing	600
Dry Servicing	600
Jet Pump Servicing	1200
Pumpdown/Breakdown Service at Home	1800
Pumpdown/Breakdown Service at Workshop	2500
Installation	1500
Un-Installation	600
Outdoor Unit Re-Installation	900
Indoor Unit Re-Installation	700



## Window AC Repair/Service Prices

Repair/Service	Spare Part Cost (INR)	Labour Cost (INR)	Total Cost (INR)
Gas Charging upto 1.5 ton	NA	NA	2400 (Not Included Leakage & Pressure Testing)
Gas Charging >1.5 to 2 ton	NA	NA	3000 (Not Included Leakage & Pressure Testing)
Repair Of Inverter PCB	NA	NA	3500 - 9000
Repair Of Non-Inverter PCB	NA	NA	1800
Repair Of Cooling Coil	1000	500	1500
Repair Of Condenser	1000	500	1500
Leakage and Pressure Testing	NA	NA	600



## Split AC Repair/Service Prices

Repair/Service	Spare Part Cost (INR)	Labour Cost (INR)	Total Cost (INR)
Gas Charging upto 1.5 ton	NA	NA	2400 (Not Included Leakage & Pressure Testing)
Gas Charging >1.5 to 2 ton	NA	NA	3000 (Not Included Leakage & Pressure Testing)
Repair Of Inverter PCB	NA	NA	4000 - 12000
Repair Of Non-Inverter PCB	NA	NA	1500
Repair Of Cooling Coil	500	500	1000
Repair Of Condenser	500	500	1000
Leakage and Pressure Testing	NA	NA	600



## AC Spare Parts Prices

Repair/Service	Spare Part Cost (INR)	Labour Cost (INR)	Total Cost (INR)
Capacitor 2-5 Mfd	250	350	600
Capacitor 10-25 Mfd	400	350	750
Capacitor 35-50 Mfd	400	350	750
Capacitor 50-60 Mfd	400	350	750
AC Fan Blade	1000	500	1500
AC Valve	900	500	1400
Compressor 0.8-1 Ton (Rs. 2500 Extra For Gas Charging)	NA	NA	6500
Compressor 1.5 Ton (Rs. 2500 Extra For Gas Charging)	NA	NA	7500
Compressor 2 Ton (Rs. 3200 Extra For Gas Charging)	NA	NA	9200




## AC Spare Parts Prices

Repair/Service	Spare Part Cost (INR)	Labour Cost (INR)
Blower	1100	500
Grill	1100	350
Fan Motor Outdoor	1800	500
LVT	900	500
Sensor	350	500
Blower Motor	2100	500
Copper Pipe (Per Metre)	750	NA
Flap/Swing Motor	400	500
Capillary and Filter	350	NA
Expansion Valve	1200	NA
Flair Nut	150	NA
Universal Remote	700	NA
Swing Blade	400	350
Connector Wire (Per Metre)	150	350



## Other AC Repair/Service Prices

Repair/Service	Labour Cost (INR)
Adjust Grill Locks	350
Adjust Pipe And Tight Compressor Screw	350
Cover All Lines By Insulation	500
Tighten/Replace Thimble	400
Replace Connector Wires(1m)	350
Replace Drain Pipe(1m)	100
Water Leakage Repaired	450



## Window AC Spare Parts Prices

Repair/Service	Spare Part Cost (INR)	Labour Cost (INR)
Copper Cooling Coil	3700	500
Grill Cover	1200	350

## Split AC Spare Parts Prices in Mumbai, Navi Mumbai and Thane

Repair/Service	Spare Part Cost (INR)	Labour Cost (INR)
Copper Cooling Coil Split	4000	500
Copper Coil Condenser 1 Ton Split	3200	500
Copper Coil Condenser 1.5 Ton Split	3500	500
Copper Coil Condenser 2 Ton Split	4000	500
Split AC Floor Stand	550	NA
Split AC Wall Stand	550	NA
Contactora (Split AC)	500	500
Contactora(Daikin/O-General)	1500	500